DPM 2389-2

received

U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

SECTION I	
MANUFACTURER'S NAME FLAMEMASTER CORPORATION / CHEM SEAL DIVISION	EMERGENCY TELEPHONE NO. (818) 982-1650
ADDRESS (Number, Street, City, State, and ZIP Code) 11120 SHFRMAN WAY, SUN VALLEY, CA. 91352	
CHEMICAL NAME AND SYNONYMS	TRADE NAME AND SYNONYMS Part A CS 7707
CHEMICAL FAMILY NYLON RESIN FORMUL	A N/A

SECTION	V II -	HAZAF	DOUS INGREDIENTS		
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST	-		ALLOYS		-
VEHICLE NYLON RESIN	8		METALLIC COATINGS		
SOLVENTS ETHYL ALCOHOL	66	1000ppr	FILLER METAL I PLUS COATING OR CORE FLUX		
ADDITIVES PHENOLIC RESIN	3		OTHERS		
OTHERS META-CRESOL	4.6				
HAZARDOUS MIXTURE	SOF	THER LIC	OUIDS, SOLIDS, OR GASES	%	TLV (Units)
					-
					1.

SECTION III - PHYSICAL DATA					
BOILING POINT (°F.)	170°F	SPECIFIC GRAVITY (H2O=1)	0.89		
VAPOR PRESSURE (mm Hg.)	40 mm	PERCENT, VOLATILE BY VOLUME (%)	70%		
VAPOR DENSITY (AIR=1)	1.4	EVAPORATION RATE (Buty) Acetate)	1.6		
SOLUBILITY IN WATER	MISCIBLE				
APPEARANCE AND ODOR CLEAR L	IQUID, ETHY	L ALCOHOL ODOR			

FLASH POINT (Method used)	70 ⁰ F		FLAMMABLE LIMITS	Lel 2 2	Uei 10
EXTINGUISHING MEDIA	CO ₂ , DRY	CHEMICALS	·····		
SPECIAL FIRE FIGHTING PRO	CEDURES	DO NOT USE	MATER		
UNUSUAL FIRE AND EXPLOSI	ON HAZARDS	FLAMMABLE	MIXTURE		

SECTION V - HEALTH HAZARD DATA					
THRESHOLD LIMIT VALUE					
EFFECTS OF OVEREXPOSURE	INTOXICATION	- DIZZINESS, MAY CAUSE EYE & EAR IRRITATION.			
INGESTION: TOXIC HAZ		2.			
EMERGENCY AND FIRST AID N	ROCEDURES				
EYES: WASH WITH SOAP	AND WATER	INHALATION: REMOVE TO FRESH AIR			
INGESTION: SEE A DOC	TOR.				

SECTION VI - REACTIVITY DATA					
STABILITY	UNSTABLE	2.54	CONDITION	S TO AVOID	
	STABLE	Х	AVOID	CONTACT WITH SKIN.	
INCOMPATABILIT	Y (Materials to avoid)	МОІ			
HAZARDOUS DEC	OMPOSITION PRODU	CTS			
HAZARDOUS MAY OCCU POLYMERIZATION WILL NOT		₹ ·		CONDITIONS TO AVOID	
		CCUR	Х	AVOID CONTACT WITH SKIN.	
			,		

SECTION VII - SPILL OR LEAK PROCEDURES					
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED					
BLOT UP WITH RAGS OR ABSORBENT. ORDINARY CLEAN-UP.					
tari da kana d					
WASTE DISPOSAL METHOD					
SANITARY LANDFILL.					

	SECTION VIII - SPEC	IAL PROTECT	TION INFORMATION
RESPIRATORY PI	ROTECTION (Specify type)		
VENTILATION	LOCAL EXHAUST REQUIRED) 4	SPECIAL
	MECHANICAL (General)	,	OTHER
PROTECTIVE GLO	YES	EYE PRO	SAFETY GLASSES
OTHER PROTECT	IVE EQUIPMENT		

SECTION IX - SPECIAL PRECAUTIONS					
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING AVOID PROLONGED BREATHING OF VAPOR					
OR SKIN CONTACT. KEEP IN TIGHT CLOSED CONT	TAIMERS.				
STORE BELOW 80°F.					

received 19-87

U.S. DEPARTMENT OF LABOR

Occupational Safety and Health Administration

Form Approved OMB No. 44-81387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

SECT	ION I
MANUFACTURER'S NAME	EMERGENCY TELEPHONE NO.
The Chem Seal Corporation	(213) 982-1655
ADDRESS (Number, Street, City, State, and ZIP Code) 11120 Sherman Way, Sun Valley,	CA 91352
CHEMICAL NAME AND SYNONYMS N/A	CS 7707 Part B
Ny lon	N/A

PAINTS, PRESERVATIVES, & SOLVENTS	*	TLV (Units)	ALLOYS AND METALLIC COATINGS	*	TLV (Units)
PIGMENTS	.		BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS Ethyl Alcohol	80	1000 pp	FILLER METAL MPLUS COATING OR CORE FLUX		
ADDITIVES		<u> </u>	OTHERS		
OTHERS					
- HAZARDOUS MIXTURE			DUIDS, SOLIDS, OR GASES	*	TLV (Units)
					ĺ
	•				

SECTION III - PHYSICAL DATA						
BOILING POINT (°F.)	170° F	SPECIFIC-GRAVITY (H2O=1)	0.89			
VAPOR PRESSURE (mm Hg.)	40 mm	PERCENT, VOLATILE BY VOLUME (%)	82			
VAPOR DENSITY (AIR=1)	1.4	EVAPORATION RATE (=1)	1.6			
SOLUBILITY IN WATER	miscible					
APPEARANCE AND ODOR	Ethyl Al	cohol Odor				

	L_3.3	-19 ^{Uei}
Chemicals		<u> </u>
se water		
lammable mixture		
	se water	se water

SECTION V - HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE 1000 ppm in air. EFFECTS OF OVEREXPOSURE
Capable of causing severe skin and eye burns.
emergency and first aid procedures For eye contact, flush with water for 15 min. Then see a doctor
immediately. For skin contact, wash thoroughly with water.

		\$	SECTI	ION VI - REACTIVITY DATA
STABILITY	UNS	UNSTABLE		CONDITIONS TO AVOID
STABLE			X	Avoid contact with skin
INCOMPATABIL		No	one	
HAZARDOUS		MAY OCCUR		CONDITIONS TO AVOID
POLYMERIZATI	ION	WILL NOT OCCUR		X
WILL		***************************************		X

SECTION VII - SPILL OR LEAK PROCEDURES	
steps to be taken in case material is released or spilled Blot up with rags or absorbent. Ordinary clean-up.	
-	
waste disposal method Sanitary land fill	

es e esperare	SECTION VIII - SPECIAL PROTECTION INFORMATION						
RESPIRATORY PI	ROTECTION (Specify type)		· · · · · · · · · · · · · · · · · · ·				
VENTILATION	LOCAL EXHAUST Require	đ	SPECIAL				
	MECHANICAL (General)		OTHER				
PROTECTIVE GLO	Yes	EVE PROJECTION Safety G	lasses				
OTHER PROTECT	IVE EQUIPMENT	· · · · · · · · · · · · · · · · · · ·					

SECTION IX - SPECIAL PRECAUTIONS	
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Avoid prolonged breathing of vapor or skin contact. Keep	
in tight closed containers.	
Store below 80° F.	· ·